

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 10

1200 Sixth Avenue, Suite 900 Seattle, Washington 98101-3140

AUG - 5 2015

OFFICE OF COMPLIANCE AND ENFORCEMENT

Reply to:

OCE-101

CERTIFIED MAIL -- RETURN RECEIPT REQUESTED

EPA WARNING LETTER

Mr. Tim Byam Plant Manager Pendleton Flour Mills LLC 501 SE Emigrant Avenue Pendleton, Oregon 97801

Re:

Inspection of Risk Management Program (RMP)

EPA RMP Facility ID# 1000 0017 7239

Dear Mr. Byam:

On June 25, 2015, the U.S. Environmental Protection Agency (EPA) conducted an inspection of the Pendleton Flour Mills LLC facility located at 501 SE Emigrant Avenue, Pendleton, Oregon. The purpose of the inspection was to evaluate compliance with Section 112(r) of the Clean Air Act also known as the Risk Management Program (RMP). The RMP inspection was conducted pursuant to the authorities under Section 112(r) and Section 114 of the Clean Air Act. Listed below are the areas of concern identified by EPA:

1. Mechanical integrity requirements: PFM has not ensured the frequency of inspections and tests of process equipment is consistent with applicable manufacturers' recommendations, good engineering practices, and prior operating experience as required by 40 CFR 68.73(d)(3). PFM could not produce documentation on the inspection and testing of the chlorine sensors in the process areas.

Please provide the documentation to substantiate that the areas of concern listed above have been corrected. A copy of the documents must be sent to Javier Morales, RMP Coordinator, within 14 days of your receipt of this letter. The documents may be sent via e-mail, fax or mail.

Javier Morales, RMP Coordinator U.S. EPA Region 10 1200 Sixth Avenue, Suite 900, OCE-084 Seattle, WA 98101 Fax: (206) 553-0124

Please refer to the document *General Risk Management Program Guidance* for additional information pertaining to the areas of concern addressed above. This guidance document can be found on EPA's website at:

http://www.epa.gov/emergencies/content/rmp/rmp guidance.htm#General

We urge you to take the steps necessary to address these concerns and to ensure that all aspects of your operation are conducted in accordance with all applicable federal, state, and local requirements. If in the future, additional violations are identified and/or corrections to the identified concerns are not made, EPA may proceed with enforcement action. If you have any questions about the inspection or the Risk Management Program, please contact Javier Morales, RMP Coordinator, at (206) 553-1255 or morales.javier@epa.gov.

Sincerely,

Kelly McFadden, Manager

Helly M Jada

Pesticides and Toxics Unit